

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)



- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)




- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)




- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)

La Cienega Avenue-McManus Avenue/Washington Blvd




- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)



- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)



- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)



- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)



- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)






- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)




- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)



- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations

Highway Safety Improvement Program (HSIP), Cycle 7

Countermeasure: S6: Provide protected left turn phase (left turn lane already exists)



- Targeted pole and foundation removals
- New foundation and pole installations
- Signal mast arm removals
- New signal mast arm installations
- Luminaire mast arm removals
- New Luminaire mast arm installations

- 3 Section VEH HD removals
- New 4/5 Section VEH HD installations
- Bulldog PPB installations
- 2" Conduit installations
- Controller cabinet upgrade
- Video Image Detection installations
- Opticom EVP removals and installations